



lite:STRIP

INSTALLATION INSTRUCTIONS


Before applying LED strip to surface, make sure you know where you want it to go and position it there to be sure it fits. Only apply to non-porous surfaces. NEVER apply to raw wood.

1. Clean the application area EVEN if it looks clean. Alcohol wipes are best for this.
2. Wait for any moisture to evaporate before applying.
3. Preposition the LED strip with painters tape or similar to make sure it fits in its desired location.
4. Peel back the brown backing tape about 3 inches and apply one end to the prepositioned area.
5. Slowly peel the backing paper while applying the strip. If you have difficulty removing this backing tape, you may find it easier to start it with a sharp-edged tool. Be sure not to touch the glue to ensure maximum adhesion.
6. After application, ensure adhesion by pressing hard on each LED with your finger. For more even adhesion, use a "J roller" with a rubber roller wheel.

Accessories


lite:HUB

Power
Supply
Required



lite:SWITCH

Optional
Remote
Switch



Questions?

732.747.4353

info@AsteriskLighting.com



Asterisk*
LIGHTING INNOVATIONS

